All data for Property of Richard Kozuma as of 12/18/2020

Help for this re-

This report contains most of the data from the facility record including inspections, MITs,

rt permit information

and project status. You can select/copy and "paste special- unformatted text" all or part of

this page

to a text document to start correspondence about the facility.

Facility

Property of Richard Kozuma 46-093 Lilipuna Rd 2 dwellings Heeia, HI 96744

GIS: 21.425, -157.795

Local Identifier: TMK 1-4-6-001-022 UIC File ID: HI-20150609-JK-787

Tribal Land: No

Ownership: Other - Individual or household

Contacts

Contact Type: Owner Richard Kozuma

PO Box 4774

Kaneohe, HI 96744

Project Status and Comments

Status	Action Date	Followup Date	Action Needed	First Mid	Last	Comments	Updated
Followup Needed	06/09/2015	~	-	-	-	2 homes potentially served by LCC. Oceanfront. 12/18/2017: DOH inspected in response to complaint. Cesspool serves 2 dwellings. 12/28/2017: DOH sent warning letter.	01/25/2018

Status	Action Date	Followup Date	Action Needed	First Mid	Last	Comments	Updated
						emailed EPA. Cesspool overflowing onto his property & wants to know when problem will be resolved. 1/10/2018: emailed DOH giving lawyer's name & wanting to know when problem will be resolved. 1/12/2018: DOH emailed be that there doesn't appear to be any ww spill onto his property. Upgrade enforcement is handled by EPA. 1/12/2018: Kozuma emailed EPA that refrigerator is in unenclosed section of home. 1/17/2018: Kate emailed still gathering info.	
Followup Needed	01/25/2018	02/26/2018	-	-		1/25/2018: Kate emailed Kozuma requesting site plan & bathroom/kitchen facilities in cottage. 1/26/2018: Lynda Pate, Lyons, Brandt, Cook & Hiramatsu, emailed response to above. Cottage has fridge but no cooking appliance. 1/29/2018: Kate spoke with	08/29/2019

Status	Action Date	Followup Date	Action Needed	First Mid	Last	Comments	Updated
Status		3				Comments Kozuma, who is working on upgrade. Kate requested update by end of 2/2018. 2/28/2018: Kozuma emailed.that leach field isn't feasible & placement of septic tank is problematic. Will make changes to home & property to accommodate Will submit monthly updates. 3/2/2018: Kate replied & said we would like monthly or quarterly updates. 5/10/2018: needs to a shoreline survey before he can move forward. Working with Engineering Dynamics. Will keep me posted. 7/5/2018: Kozuma emailed the project is back on track after delay due to issues with neighbor. 8/17/2018: Kozuma phoned - still property line issues with neighbor. Owner still working on upgrading the cesspool. 9/24/2018:	Updated
						Neighbor re-emailed his previous email, requesting response. 9/25/2018: Kate replied that progress is being	

Status	Action Date	Followup Date	Action Needed	First Mid	Last	Comments	Updated
Status					Last	monitored but no additional info at this time. 5/20/2019: emailed that the Kozuma's have vacated the property but the cesspool is still being pumped every 30 days & requested status update. 7/30/2019: emailed that there is e.coli in the groundwater on his property near Kozuma's cesspool. 8/27/2019: DOH	Updated
						issued field citation to [] (neighbor) for illegally adding bathroom to detached garage structure & connecting to existing cesspool (which then became classified as an LCC).	

Well Summary

1 - Active - 5W10 Large Capacity Cesspool - as of 06/09/2015

Named Wells

Count/	Well Name
1	No data

Other Ground Water Considerations For Facility

No Non-UIC Discharges recorded.

Inspections in the last 10 Years

No inspections recorded in iWells database over the last 10 years.

Class V Closure Action(s)

No Closure actions have been recorded for wells at this facility.

Mechanical Integrity Tests

No mechanical integrity tests found.

Permit & Permit Activity

No permit or permit activity found.

Violations

No violations found.

Attachments - Not Confidential

File Name	Doc Sign Date	Doc Category	Doc Caption	Added Date	Added By
146001022 Kozuma Email1-12- 18complaint.pdf	01/12/2018	Characterization	Cesspool Overflowing onto Neighboring Property	01/16/2018	JKERPEL
146001022 Kozuma Email1-25-18.pdf	01/25/2018	Characterization	Request for Site Plan & Cottage Details	01/25/2018	JKERPEL
	02/28/2018	Compliance		03/01/2018	JKERPEL

File Name	Doc Sign Date	Doc Category	Doc Caption	Added Date	Added By
146001022 Kozuma Email2-28-18.pdf			Problems with Septic Tank & Leach Field Siting		
146001022 Kozuma Investigation.pdf	12/18/2017	Characterization	DOH Complaint Investigation Report	01/11/2018	JKERPEL
146001022 Kozuma Warning.pdf	12/28/2017	Characterization	DOH Warning Letter	01/11/2018	JKERPEL
146001022 Kozuma Email1-12-18b.pdf	01/12/2018	Characterization	Refrigerator in Unenclosed Section of Home 2	01/16/2018	JKERPEL
146001022 Kozuma Email1-12-18a.pdf	01/12/2018	Characterization	Refrigerator in Unenclosed Section of Home 1	01/16/2018	JKERPEL
146001022 Kozuma Email1-17-18.pdf	01/17/2018	Characterization	No Spill, EPA Coordinates LCC Upgrades	01/18/2018	JKERPEL
146001022 Kozuma Email5-10-18.pdf	05/10/2018	Compliance	Engineering Dynamics Is PE	05/10/2018	JKERPEL
146001022 Kozuma Email1-29-18.pdf	01/29/2018	Compliance	LCC to be Replaced by Septic	01/29/2018	JKERPEL
146001022 Kozuma Site.pdf	01/26/2018	Characterization	Site Plan & Cottage Details	01/29/2018	JKERPEL
146001022 Kozuma Email3-2-18.pdf	03/02/2018	Compliance	EPA Would Like Monthly or Quarterly Updates	03/05/2018	JKERPEL
146001022 Kozuma Email7-5-18.pdf	07/05/2018	Compliance	Delay Due to Issues with Neighbor	07/09/2018	JKERPEL
146001022 Kozuma Email7-30-19.pdf	07/30/2019	Compliance	Cesspool May Be Contaminating Neighbor's Property	08/12/2019	JKERPEL
146001022 Kozuma Email5-20-19.pdf	05/20/2019	Compliance	Neighbor Requesting Status Update	05/30/2019	JKERPEL

Enforcement Actions

No Enforcement data has been added.

Property of

14882 JKERPEL Richard

Kozuma

08/29/2019

release 2.02010 <u>Set Screen Reader Mode On</u>